



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Supervisor DRH

Minerals Regulatory Program

Date of Report: August 29, 2007

Mine Name: Developments 1 and T & M Holdings

Permit number: S0350023 and
S0350033

Operator Name: Decorative Developments and Decorative
Landscaping

Inspection Date: August 28,
2007

Time: 9:15 to 10:25 AM

Inspector(s): Paul Baker

Other Participants: Ben McInnes

Mine Status: Active

Weather: Partly cloudy, 70s

Elements of Inspection

	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

The operators were required by two separate cessation orders (for the two mining operations) to consolidate operations within permitted areas. The purpose of the inspection was to see whether this had been done.

Inspection Summary:

7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)

The operator has, as required, marked the disturbed area boundaries and has consolidated rock into the disturbed areas. The remaining areas are rough with a moderate amount of rock on the surface, and they are ready to be seeded.

Conclusions and Recommendations:

The operator has complied with the portions of the cessation order requiring that operations be consolidated. The graded areas will need to be seeded this fall with perennial species, and this will complete the abatement.

Page 2 of 2

Inspection Date: August 28, 20007; Report Date: August 29, 2007
S0350023 and S0350033

Inspector's Signature

REBRE

Date:

9/4/07

PBB:pb

cc: Ben McInnes and Tracy Burnham, Decorative Developments and Decorative Landscaping

P:\GROUPS\MINERALS\WP\M035-SaltLake\S0350023-DecorLandscape\inspections\ins-08282007-decorative.doc